

Method card

BUZIL-WERK Wagner GmbH & Co. KG

CORRIDOR® GLORIN S 734

Application area: Floor / coating pH 7.5				
Dilution	pure	high speed		
Suitable for	Public institutions, offices	Not suitable for	Textile surfaces; Unsealed parquet	
Application	Water-resistant floor coverings; Linoleum; PVC; Rubber; Coatable polyurethane coated coverings			
\wedge	Issue / Failture / Requirement	Solving Issue		
Trouble	■ Poor penetration / shine	 Covering too porous, apply pore filler / another layer 		
Shooting	■ Foaming with "craters" as a result after drying	 Covering too rough, spread more slowly when applying 		
	Powdering off when used	 Before applying, do not let the covering dry / deep clean again 		
Before initial	■ Severe marking when used	 Intensive cleaning with Maradin HC 43, Aktiv G 433, spray cleaning with Corridor® Spray S 770 		
Test material compatibility!	• Grey / mat appearance of sur- face due to hard water	Clean periodically with O Tens Azid G 501		
	Damage on surface (discoloration, material swelling, etc.)	 Check material's chemical and water resistance 		



Method card

BUZIL-WERK Wagner GmbH & Co. KG

ALTERNATIVE PRODUCT | CORRIDOR® GLORIN S 734

Application area: Floor / coating pH 7.5				
Alternative Product	Differentiation	Application		
Planta® Multi Gloss P 320	Eco certified	Glossy floor coating		
Corridor® Complete S 732	Contains metallic salts	Glossy floor coating		
Corridor® Matt S 737	Suitable for sports flooring (DIN 18032/2)	Silk matt floor coating		
Corridor® Jewel S 741	More shine	High-gloss floor coating		